# MARYLAND INVENTORY OF Maryland Historical Trust HISTORIC PROPERTIES State Historic Sites Inventory Form

Survey No.	B-424-
Magi No.	
DOE yes	no

1. N	lame	(indicate pref	erred name)		
historic		315 West I	Baltimore Stree	t	
and/or co	ommon	Avis Rent-	-A-Car/Parking		н
2. L	.oca	tion			
street &	number	315 W. Bal	timore Street	-	not for publication
city, towr	n	Baltimore	vicinity of	congressional district	Seventh
state		Maryland	county	Baltimore	)
3. C	Class	ification			
	rict ding(s) cture	Ownership  public private both  Cublic Acquisition in process being considered not applicable	Status Xoccupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture X commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. (	Owne	r of Proper	y (give names a	nd mailing addresse	s of <u>all</u> owners)
name		Sally Sue	Thomas		-
street & I	number	6615 Reist	erstown Road,	Room 301 telephone n	o.:
city, tow	n	Baltimore	state	and zip code	MD 21215
5. L	.oca	tion of Lega	l Descripti	on	
courthou	use, registr	y of deed Banktimore	City Courthous	е	SINDERO3
street &	number	100 N. Cal	vert Street, R	oom 610	fol <b>ig</b> 5
city, tow	n	Baltimore		state	MD
6. F	Repre	esentation i	n Existing	Historical Surv	eys
title					
date				federal stat	te county loca
posito	ory for surv	rey records	-		
city, tow	n			state	

-	-							
7	n	20	~		-	**	-	-
7.		53	6	11	w		u	ш
	-			ابطاه	•		_	ķ

Survey No. B-4421

						•
Condition		Check one	Check one	20		
excellent	deteriorated	unaltered	_X original s	site		
x good	ruins	X altered	moved	date of	move	*****
fair	unexposed					

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

#### Resource Count: 1

This circa 1960 parking garage, currently a car rental business, faces north on West Baltimore Street and abuts two partywall structures. The concrete structure is two bays wide and four stories high. The street frontage is 64'1" and the depth is 171'6".

The first story has a large open bay to the east with three painted rows demarcating the entrance/exit. Three stop and go traffic lights are positioned over the top of the bay. The rental office is in the second bay. It has a glazed window wall that is subdivided into six sections. Double glass doors fill the first two bays, and a window band fills the remaining four bays. The windows are set above a ginder block foundation. The wall around the rental office is also set in cinder block. The east side of the rental office is a glass curtain wall with a glass door; this wall faces into the garage.

The upper parking tiers have low concrete walls that are open to the elements. The three concrete walls are embellished with three incised horizontal grooves. A row of posts divide the first and second bays. The rooftop parking has no overhead shelter.

The interior of the garage has reinforced concrete ceilings supported by structural bays of concrete lintels and posts.

8. Si	ignificance		Survey No.	B-4421
Period prehis 1400 1500 1600 1800 X 1900	1499 archeology-historic 1599 agriculture 1699 architecture 1799 art 1899 commerce	community planning conservation economics education engineering exploration/settlement	iterature military music	religion science sculpture social/ humanitarian theater X transportation other (specify
Specific o	dates	Builder/Architect	ınknown	
	Applicable Criteria:A and/or Applicable Exception:		E F G	

Prepare both a summary paragraph of significance and a general statement of history and support.

Level of Significance: national state X local

This 1960s parking structure is a significant building type in the Baltimore commercial streetscape. The need for parking structures is a twentieth-century phenomenon that accompanied that rise of the automobile--a need that burgeoned in the post-war period. The four-story height of this structure indicates the increasing density of traffic and the need for parking in the downtown district, a need for both office workers and shoppers. The garage also indicates the prevalence of commuter traffic in the downtown area in the post-War period and, as such, makes a contrast with the residential nature of the downtown in the nineteenth-century. The location of the parking structure also indicates the heavy traffic along Baltimore Street.

The style of the garage is a good example of a circa 1960s functional aesthetic. Similarly, the interior of the garage exposes its internal structure. The reinforced concrete posts and beams form a functional aesthetic which is deemed appropriate for the structure and is typically never covered up.

The conversion of the space to a car rental agency and their parking lot is an interesting twist in this building's role as a transportation oriented facility.

## 9. Major Bibliographical References

Survey No.

B-4421

Richard Longstreth, The Buildings of Main Street (Washington: Preservation Press, 1987).

-	ieograpi	nical Data						
Acreage of nominated property  Quadrangle name  UTM References do NOT complete UTM references				Quadrangle scale				
A L L	Easting	Northing	Zone	e Easting	ا السا	rthing		
الياء	لتبليل	لبياباليا	ا ۵	بيا ل	نا لنبا	لبليا		
ELLL	لببليا	ليلليا	FLL	علا ل	يا لينيا			
GLI L		ليبليل	н	علا ل	نا لنبيا			
List all sta	tes and countie	s for properties over	erlapping state or county	county bo	undaries	code		
state		code	county			code		
		nared Ry						
11. F	orm Pre	pareu by						
		Architectura	al Historian					
	Diane Shaw,	Architectura	al Historian		cember 21	, 1991		
name/title organization	Diane Shaw,	Architectura		De	cember 21 301-396-			

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUS DHCP/DHCE 100 COMMUNIAY FLAGA CROWNSVILLE, MID 21032-2023

### COMPREHENSIVE PLAN DATA

## **HISTORIC CONTEXT:**

Geographic Organization: Piedmont

Chronological/Developmental Period:

Modern Period, 1930-present

Historic Period Themes: Architecture Economics

Resource Type:
Building

Historic Environment: Urban

Historic Function and Use:

Transportation

Known Design Source: None

CED BY P. WAINWRIGHT

ECKED BY

NOTICE

THIS IS A REAL PROPERTY PLAT AS PROVIDED FOR UNDER ARTICLE 76(d) OF THE CITY CHARTER IT IS COMPILED FROM TITLE AND OTHER SOURCES AND IS NOT AN AUTHENTIC SURVEY.


CITY OF BALTIMORE
DEPARTMENT OF PUBLIC WORKS

PROPERTY LOCATION DIVISION

WARD 4 SECTION 10 BLOCK 643

SCALE 1"50"0" DATE DEC.1966

B-4421 Avis Rent-A-Car/Parking 315 W. Baltimore Street Block 643 Lot 006 Baltimore City Baltimore East Quad.





B-4421
315 W. Baltimore St. / Aris Rental
Baltimore MD
Diane Shaw
8/91
Maryland SHPO
Facade, north elevation